



**EVOTECH**®  
P E R F O R M A N C E

[www.evotech-performance.com](http://www.evotech-performance.com)


Triumph Tiger 1200  
Garmin Sat Nav Mount




## Kit Contents

- |  |   |
|--|---|
| (A) 1 x Main Plate                       | (L) 2 x M4 x 5mm Black Button Head Bolts  |
| (B) 1 x Pivot Plate                      | (M) 4 x M4 x 10mm Black Button Head Bolts |
| (C) 1 x Sub Mounting Bracket             |   |
| (D) 2 x M5 x 8mm Black Button Head Bolts |   |
| (E) 2 x P-clips (No.1)                   |   |
| (F) 2 x P-clips (No.2)                   |   |
| (G) 2 x P-clips (No.3)                   | Sub Kit                                   |
| (H) 2 x P-clips (No.4)                   | (AA) 2 x M5 x 25 Silver Button Head Bolt  |
| (I) 2 x Lobe Screw                       | (BB) 2 x M5 x 20 Silver Button Head Bolt  |
| (J) 2 x M5 Black Washer                  | (CC) 4 x Top Hat Spacer                   |
| (K) 2 x Locking Washer                   |   |


P E R F O R M A N C E









P E R F O R M A N C E








P E R F O R M A N C E







EP<sup>®</sup>  
PERFORMANCE




EVERTECH<sup>®</sup>  
P E R F O R M A N C E










Repeat  
Both Sides













®  
H  
N C E  
®



Ensure Seal  
Isn't Trapped







## ESSENTIAL CHECKS



It is recommended that periodic inspections are made to ensure that all bolts are tightened to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced



**EVOTECH**®  
P E R F O R M A N C E

[www.evotech-performance.com](http://www.evotech-performance.com)