




www.evotech-performance.com MV Agusta Quadlock Mount Installation Instruction





R























8

R


























It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced



www.evotech-performance.com